
UPDATED CATEGORY CODE BOOK

TO: ALL USERS OF 2024 CATEGORY CODE BOOK *By: [Signature]*
FROM: *for* DIRECTOR ERIC E. MARABELLO, P.E.
SUBJECT: DISTRIBUTION OF UPDATED CATEGORY CODE BOOK
DATE: January 15, 2025
RESPONSE
REQUESTED N/A
BY:

PURPOSE

To provide updates to the 2024 State Highway Administration (SHA) Category Code Book. These updates are listed below.

SUMMARY

The latest version of our Category Code Book, dated January 15, 2025, is located on the SHA Internet website at <https://roads.maryland.gov/mdotsha/pages/index.aspx?PageId=33>. All contracts with applicable items advertising on or after January 28, 2025, must include these revised category codes. Advertised contracts that require an addendum for some other reason should include these revised category codes, if applicable. The following category codes were suppressed or added:

CATEGORY 400 – STRUCTURES

The following pay items have been suppressed:

438112	PNEUMATICALLY APPLIED MORTAR	CF
435140	TYPE IV DECK REPAIR	SF

The following pay items have been added:

413100	MICROPILE	LF
413105	EXCESS GROUT	CY

The following pay items have been added, continued:

413110	MICROPILE PROOF LOAD TEST	EA
413115	MICROPILE VERIFICATION LOAD TEST	EA
435131	TYPE II DECK REPAIR	CF
435136	TYPE III DECK REPAIR	CF
435143	REHABILITATION OF CONCRETE STRUCTURES	CF
459080	STRUCTURAL STEEL BEAM RETROFIT	EA
459104	REMOVE AND REPLACE BRIDGE BEARING	EA
475360	ORNAMENTAL ANTI-CLIMB SHIELD	EA
463126	POURABLE JOINT SEALANT	LF
463127	PREFORMED SILICONE SEAL	LF
463128	NEOPRENE COMPRESSION SEAL	LF
463129	TESTING EXPANSION JOINTS IN STRUCTURE	EA

CATEGORY 500 – PAVING

The following pay items have been suppressed:

571140	FILLER REMOVAL	LF
571145	CRACK SHAPING	LF
571150	CRACK FILLING	LF
571155	PATCHING MATERIAL FOR CRACKS	LF

Updates to the Category Code Book
Page Three

The following pay items have been suppressed, continued:

571160	CRACK SEALER	LF
571172	SEALING CRACKS IN ASPHALT PAVEMENT	LF
571200	SAW CUTTING	LF
599250	JOINT AND CRACK SEALING MATERIAL	LB

The following pay items have been added:

571156	CRACK SEALER WITHOUT ROUTING	LF
571157	CRACK SEALER WITHOUT ROUTING	LM
571158	CRACK SEALER WITHOUT ROUTING	LB
571161	CRACK SEALER WITH ROUTING	LF
571162	CRACK SEALER WITH ROUTING	LM
571163	CRACK SEALER WITH ROUTING	LB
571166	ASPHALT REPAIR MASTIC	GAL

If there are any questions regarding this update, please contact Jared Paper-Evers, P.E., SHA Office of Highway Development (OHD) Assistant Division Chief, at 410-545-8400, or via email at jpaperevers@mdot.maryland.gov. He will be happy to assist you.

cc: Benjamin Gilardi, P.E., Division Chief, OHD, SHA
Jared Paper-Evers, P.E., Assistant Division Chief, OHD, SHA